



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

Thrust Washer

| Applicaition For | Engine Model | PCS/SET |
|------------------|---|---------|
| ACURA | B17A1, B18A1, B18B1, B18C1, BA8C5D16A1, D25A1, D25A4 | 2 |
| ACURA | F22B1 SOHC 16 Valve | 2 |
| ACURA | C25A1 SOHC 24 Valve , C27A1 SOHC 24 Valve | 2 |
| ACURA | 6VD1(Isuzu engine. SOHC 24 valve) , 6VE1 (Isuzu engine. SOHC 24 valve) | 2 |
| | | |
| AUDI | BBY,AFM,ATL,BHC,AEH,AJP,AKL,APE,AQE,ARH | 2 |
| AUDI | BAD,JK,RA,SB,AAZ,AFF,APD,AGR,AHH,AHU,ALH,AFN,ASN,AVG,APD,AJM,ATJ | 4 |
| AUDI | CN, DE ,NC ,GV, JY, WH ,WN ,WR ,WX ,KE ,KF ,HY | 4 |
| AUDI | AFB,AKN,AKE,AYM,BAU,BCZ,BDG,BDH,BFC | 4 |
| AUDI | AHL,ARM | 4 |
| AUDI | AGA,AJG,ALW,AML,AMM,APC,APS,APZ,ARJ,ARM,ASM,BDV, | 4 |
| | | |
| AUSTIN | 34T, 38J/38T/38VD | 4 |
| AUSTIN | A SERIES, A+ SERIES 2965/2934 , | 4 |
| AUSTIN | A SERIES O.H.C, R SERIES O.H.C, E SERIES O.H.C, | 4 |
| AUSTIN | B SERIES 2955/2953 , 0 SERIES O.H.C, | 4 |
| | | |
| BEDFORD | 4FC1,4FD1 | 2 |
| BEDFORD | 200 Diesel, 220 Diesel, 300, 300 Diesel, 300 Diesel | 4 |
| BEDFORD | 220 Diesel, | 4 |
| BEDFORD | 466 Diesel, 500 PHASE I Diesel, 60 SERIES Diesel | 4 |
| | | |
| CHRYSLER | J8S 708,J8S 890 | 4 |
| CHRYSLER | OM 665.9 | 4 |
| | | |
| CUMMINS | 448CID,H135,495CID,464CID,672CID,743CID,855CID,927CID | 4 |
| CUMMINS | 352CID, 378CID | 4 |
| CUMMINS | 611CID, 661CID | 4 |
| CUMMINS | 903CID | 4 |
| CUMMINS | 2301 CID, 3068CID, KT38, KTA38, KTTA38, KT50, K50 | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | |
|---------------|---|---|
| DAF | 688.02, 688.13 | 2 |
| DAF | 810.03 | 2 |
| DAF | 810.29 | 2 |
| DAF | ET70, XD3P, XD3T | 4 |
| DAF | DH825, DHB825, DHR825, DHT825, DU825, H825, S825 | 4 |
| DAF | LT160, T195, LT210, DK1160, DKB1160, DKS1160, WS225, WS242, WS295 | 4 |
| | | |
| DAIHATSU | EB, EF | 2 |
| DAIHATSU | CB, CL, CD, CB-T | 2 |
| DAIHATSU | ED | 2 |
| DAIHATSU | CB-T, CL-T | 2 |
| DAIHATSU | HC, HD | 2 |
| | | |
| MERCEDES-BENZ | OM615, OM616, OM617, | 4 |
| MERCEDES-BENZ | OM601, OM602, OM603,OM604, OM605, M102, M103, M104, | 4 |
| MERCEDES-BENZ | OM501 LA, OM502LA, | 4 |
| MERCEDES-BENZ | Mill, M112 | 4 |
| | | |
| FIAT-IEVCO | 100D.000 | 4 |
| FIAT-IEVCO | 100G,127A/A.000, 200B, 141B.000, 127AB/AJ/AE, 146A6/A9.000 | 2 |
| FIAT-IEVCO | 127AB/AJ/AE, 146A6/A9.000, | 2 |
| FIAT-IEVCO | 124A, 125B, 128A, 138A, 146A, 160A1, 149A3, | 2 |
| FIAT-IEVCO | 131A, 132A, 138AR, 149B, 146A, 160A1, 1498A3, | 2 |
| FIAT-IEVCO | 115.000, 116, | 4 |
| FIAT-IEVCO | 822.615, | 4 |
| FIAT-IEVCO | B25/637 Diesel, | 4 |
| FIAT-IEVCO | 8210,8215.02,8215.22, | 4 |
| FIAT-IEVCO | CO3, | 4 |
| FIAT-IEVCO | 8210.42 | 4 |
| FIAT-IEVCO | 8210.41 | 4 |
| FIAT-IEVCO | 8030.2,8040.2,8062.24,8065,806.A, | 2 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | |
|------------|--|-----|
| FIAT-IEVCO | 8040.05, 8340.04, 8360.03, 8361.04, | 4 |
| FIAT-IEVCO | CP3.Diesel, | 4 |
| FIAT-IEVCO | 220/203, 8200.03, 200.02 | 4 |
| | | |
| FORD | 975, GSF, HCS, JLA | 2 |
| FORD | C.V.H Leanburn, C.V.H O.H.0 | 2 |
| FORD | 1.3 O.H.C, 1.6 C.H.C, 1.8 O.H.C,1993, 1294 | 4 |
| FORD | 101/2601E, 2603E, 3012E | 4 |
| FORD | 159 OHV, 171 OHV, HF23, V6 | 4 |
| FORD | 220 Diesel, 330 Diesel, 2701 E, 2704E, 2711 E, 2715E,360,589E ,590E,592E | |
| | | |
| HINO | DM100, Dq100 | 4 |
| HINO | DS50, DS60, DS70, DS80, | 4 |
| HINO | EB100, EB200, EB300, EB400, | 4/3 |
| HINO | EC100, EH100, EH300, EHSO0, EH700, | 4 |
| HINO | EF100, EF300, EF350, EF500, EF700, EG100, | 3/4 |
| HINO | EF550, EF750, F17C, F17D,F17E,F20C,F21C, | 3/4 |
| HINO | EK100, EK100-T, EK130-T, EK200, K13D, K13U, K13C, K13D, | 3/4 |
| HINO | EL100, EM100, EP100, PO9B-T, M10U, PO9C-T, P11C, | 4/4 |
| HINO | HO6B, HO6B-T, HO6C-T, HO7C, HO7C-T, HO6C-T1, HO7D, | 4 |
| HINO | V21C, V22C, V25C, V25C, V26C, V22D, | 4/4 |
| HINO | WO4C-T, WO4D, WO4D-T, WO6D, WO6D-T, WO6E, | 4 |
| HINO | PO9C-T, P11C, | 4 |
| HINO | DK10, DK20, ED100, ED100-T, ER100, ER200 | 3/4 |
| | | |
| HONDA | A18A,A20A, C20A,D12A,D13C, D13A, D15Z, D15B, EC, EE, ED, EM, EP, EN, EV | 2 |
| HONDA | B16A, B18A, B20A, B21A, D16A, ZC | 2 |
| HONDA | C25A, C27A | 2 |
| HONDA | E05A, EH | 2 |
| HONDA | F18B, F20B, F20A, F22A, H22A | 2 |
| | | |
| HYUNDAI | G4JS (Model: Sonata) | 2 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | |
|-----------|--|---------|
| HYUNDAI | G4GF(Model:Elantra 1.6L) | 2 |
| | | |
| ISUZU | 3AB1, 3AD1, 2AE1, 3AE1, 3AF1, C221, C240,, 4JB1 | 2 |
| ISUZU | 4BA1, 4BB1, 4BC1, 4BC2, 4BD1, 4BG1, 6BB1, 6BD1, 6BF1, 6BG1 | 4 |
| ISUZU | C190, C223, C223-T, D201, 4JA1, 4JC1, 4JE1, 4JF1 | 2 |
| ISUZU | C330, D500, D500-T | 4 |
| ISUZU | DAI20, DA640, GD150, DA220 | 4 |
| ISUZU | D920, E110, DH100, DH100-T, 6QA1, 6QB2 | 4 |
| ISUZU | E120, E120-T | 4 |
| ISUZU | 4EC1,4EC1-T, 4EE1-T | 2 |
| ISUZU | 4FA1,4FB1,4FC1,4FD1,4FE1,4FG1, G200,4ZA1,4ZB1,4ZC1,4ZD1,4ZE1 | 2 |
| ISUZU | 4HF1, 4HE1-T, 4HG-1,4HJ-1, 6HE1, 6HE1-T | 3 |
| ISUZU | G130, G150, G161, G180, G200 | 2 |
| ISUZU | 8PA1,8PB1,8PC1,10PA1,10PB1,10PC1, 12PA1,12PB1,12PC | 4 |
| ISUZU | 8PD1,10PD1,12PD1 | 4 |
| ISUZU | 6RA1,6RB1,6RB2,6RA1-T,6RB1-T | 4 |
| | | |
| KHD/DEUTZ | F2L 912D | 2 |
| KHD/DEUTZ | F3L 912D, F4L912D,F4L 912D, F5L912D, F6L912D | 2U/2L+2 |
| | | |
| KIA | B6 Mazda SOHC 16 Valve, BP Mazda SOHC 16 Valve, DC DOHC 16 Valve | 2 |
| KIA | FE Mazda DOHC 16 Valve | 4 |
| KIA | G4JS DOHC 16 Valve | 2 |
| | | |
| KOMATSU | 2D92, 2D92-1, 2D94-1, 2D94-2, 3D94-2, 4D92, 4D92-1, 4D92-2 | 3 |
| KOMATSU | 3D95S-W-1, 4D95L-1, 4D95S-1, S4D95L-1/T, 6D95L-1, S6D95L-1/T | 3 |
| KOMATSU | 4D105, 4D105-1, 4D105-3, S4D105, S4D105-1, 54D105-3 | 3 |
| KOMATSU | 4D105-5, S4D105-5/T, 6D105-1, S6D105-1/T, 6D110-1/T | 3 |
| KOMATSU | 4D120-1/T, S4D120-1/T, 4D130-1, S4D130-1/T | 3 |
| KOMATSU | 6D108, SA6D108, SA6D108-T | 3 |
| KOMATSU | 4D155-4, S4D155-4,6D155-4, S6D155, S6D155/T, SA6D155-4 | 3 |
| KOMATSU | 6D125-1, S6D125-1/T, SA6D125 | 3 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | |
|-----------|---|---|
| KOMATSU | S6D140-1/T, SA6D140-1 | 3 |
| KOMATSU | S6D170-1/T, SA6D170-1 | 3 |
| | | |
| LADA | 1200 O.H.C, VAZ2108,1300 O.H.C, 1500 O.H.C, 1499, 1600 O.H.O | 2 |
| | | |
| LANDROVER | 2.3L Diesel, 2.5L Diesel, 12J Diesel | |
| | | |
| LEXUS | 2VZFE Toyota DOHC 24 valve, (Model:ES250) 3VZFE Toyota DOHC 24 valve, (Model:ES300) | 4 |
| LEXUS | 1MZFE Toyota DOHC 24 valve, (Model:RX300) | 4 |
| LEXUS | 1UZFE Toyota DOHC 32 valve, (Model:LS400) | 4 |
| | | |
| LEYLAND | B SERIES, O SERIES O.H.O | 4 |
| LEYLAND | 34T, 38J, 38T, 38VD, 4/98/3749, 51UD, 57J, 57JC, 57VD | 4 |
| LEYLAND | 3.354.2, 6.354.4 | 4 |
| | | |
| MAN | 712.03, 712.04 | 4 |
| MAN | D0834, D0836 | 4 |
| MAN | D2066, D2866, D2876, E2866, G2866 | 4 |
| | | |
| MAZDA | B1, B3, B5, B6, 8J, 8F, | |
| MAZDA | D5, EI, E3, E5, TC, UC, | 4 |
| MAZDA | FP, FS, | 2 |
| MAZDA | HA, SL, SL-T, | 4 |
| MAZDA | KJ, KL, | 4 |
| MAZDA | MA, NA, UB, VB, VC, | 4 |
| MAZDA | PB, TA, TB, | 4 |
| MAZDA | PC, TC, | 4 |
| MAZDA | PN, | 2 |
| MAZDA | R2, RF, RF-T, | 4 |
| MAZDA | S2, | 4 |
| MAZDA | TF, TM,. | 4 |
| MAZDA | XA, XB, | 4 |
| MAZDA | YA, ZB, | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | |
|------------------|---|---|
| mitsubishi | 3G81, 3G82, 3G83, | 2 |
| mitsubishi | 4G41, 4G42, | 2 |
| mitsubishi | 4G63, | 2 |
| mitsubishi | 6G71, 6G72, | 4 |
| mitsubishi | 6G74, | 2 |
| mitsubishi | 4G91, 4G92, 4G93, 4G93-T, | 2 |
| mitsubishi | 4M40, | 4 |
| mitsubishi(FUSO) | S2E, S3E, S4E, S6E, | 3 |
| mitsubishi(FUSO) | S4K, S6K, | 3 |
| mitsubishi(FUSO) | S4S, S6S, | 3 |
| mitsubishi(FUSO) | 4D30, 4D31, 4D31-T, 4D32, 6D31, 6D31-T, 6DS1, 6DS3, 6DS5, 6DS7, | 3 |
| mitsubishi(FUSO) | 4D33, 4D34, 4D35, 4D36, | 3 |
| mitsubishi(FUSO) | 6D14, 6D15, 6D16, | 3 |
| mitsubishi(FUSO) | 6D20, 6D21,6D22, 6D23, 6D24, 6DC2, | 3 |
| mitsubishi(FUSO) | 6DB1, 6DB1-T, | 4 |
| mitsubishi(FUSO) | 8DC8,8DC9, | 3 |
| mitsubishi(FUSO) | 4DR5, 4DR7, 4DR6-T, 6DR5, | 3 |
| mitsubishi(FUSO) | 4M51, 4M50-T, | 4 |
| mitsubishi(FUSO) | 6M61, 6M60-T, | 3 |
| mitsubishi(FUSO) | 8M20, 8M21, | 3 |
| NISSAN | ,CG10DE, CG13DE | 2 |
| NISSAN | GA13, GA14, GA15, GA16, QG | 2 |
| NISSAN | J, J13, J15, J16, J18 | 4 |
| NISSAN | MA09, MA10 | 2 |
| NISSAN | SR18, SR20 | 2 |
| NISSAN | VQ20DE, VQ25DD, VQ25DE, VQ30DD, VQ30DET, VH41, VH45 | 4 |
| NISSAN | VH41, VH45 | 4 |
| NISSAN DIESEL | BD30, QD32, QD32-T, TD23, TD25, TD27, TD27-T, Sd20, Sd22, Sd33 | 4 |
| NISSAN DIESEL | ED30, ED33, ED35, FD33, FD35, FD35-T, ED6, FD6, FD6-T | 4 |
| NISSAN DIESEL | FE6, FE6-T, FD42, FE46, FD46-T, FD46-TA | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | |
|---------------|--|---|
| NISSAN DIESEL | ND6, ND6-T, NE6, NE6-T | 4 |
| NISSAN DIESEL | PD6, PD6-T, PE6, PE6-T, PE6H, PE6H-T, PP6H | 4 |
| NISSAN DIESEL | PF6, PF6-T, PG6, PG6H . | 4 |
| NISSAN DIESEL | RD8, RD8-T, RE6, Rf8 | 4 |
| | | |
| PERKINS | A4.212, A4.236, 4.40, A4.354.4,T4.40, 4.248, (U5LT 0265) (Model:MF265) | 4 |
| PERKINS | AD3.152, AT3.152, (U5LT 0260) (Model:MF165) | 4 |
| | | |
| PEUGEOT | TU1, TU2, TU3A, TUD3, TUD5, TU9, TU9M, (Model:104,106,205,309) | 2 |
| PEUGEOT | 10AE11, 3E1A, E1A, 10AG12/2, (Model: 205,309) | 2 |
| PEUGEOT | XU5, XU7, XU9, XUD9, (Model: 305,405,309) | 4 |
| PEUGEOT | XC7, XM7, XNI/2, XNIA, (Model: 404, 504, 505) | 4 |
| PEUGEOT | U8, XD2S, XD3I, XD2, XD3, (Model: 505,604) | 4 |
| | | |
| RENAULT | Z7X, Z7V, ZM, X7W8700 | 4 |
| RENAULT | 807, 688, 688.02, 810, 821, 841, 843, CIE715 | 2 |
| RENAULT | E7P, F8M, F2N, F3N, F8Q | 2 |
| RENAULT | 829, J6R, 852.02, 852, J5R, J5R 716/800 | 2 |
| RENAULT | 06.20.45 | 4 |
| RENAULT | 06.35.40 | 4 |
| | | |
| SCAN IA | DS9, DSC9 | 4 |
| SCAN IA | D10,D11 | 4 |
| SCAN IA | D11, DS11, DSC11, DSC14, DS14, D14 | 4 |
| | | |
| SUZUKI | F5A, F5A-T | |
| SUZUKI | F8A, F10A, F8B, (Y64) | |
| SUZUKI | G10, G10-T, G13A, G13B, G13BA | |
| SUZUKI | G15A, G16A, G16B | |
| | | |
| TOYOTA | 1A, 2A, 3A, 4A, 4A-GZE,5A, 7A-FE | 4 |
| TOYOTA | B, 2B, 3B, 11B, 13B, 13B-T, 14B, 14B-T | 4 |
| TOYOTA | 1C, 2C, 2C-T, 3C-T | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | |
|------------|---|---|
| TOYOTA | D, 2D | 4 |
| TOYOTA | 1DZ, 1HZ, 1HZ-T, 1HD-T, 1PZ | 4 |
| TOYOTA | 1E, 2E | 4 |
| TOYOTA | 3E | 4 |
| TOYOTA | 3F | 4 |
| TOYOTA | 1FZ | 4 |
| TOYOTA | 1G, 1G-GTE | 4 |
| TOYOTA | H, 2H, 12H-T, J, 2J, 5P | 4 |
| TOYOTA | 1JZ, 2JZ | 4 |
| TOYOTA | K, 2K, 3K, 4K, 5K, 7K, 1N, 1N-T | 4 |
| TOYOTA | 1KZ-TE | 4 |
| TOYOTA | L, 2L, 2L-T, 3L | 4 |
| TOYOTA | M, 2M, 3M, 4M, 5M, 6M, 7M, 5R | 4 |
| TOYOTA | 3P, 4P | 4 |
| TOYOTA | 2R, 12R | 4 |
| TOYOTA | 6R, 7R, 8R, 10R, 16R, 18R, 19R, 20R, 21R, 22R | 4 |
| TOYOTA | 1RZ, 2RZ, 3RZ | 4 |
| TOYOTA | 1S, 2S, 3S, 4S, 5S, T, 2T, 2T-G, 3T, 3T-G, 4T-G, 12T, 13T, 1Y, 2Y, 3Y, 4Y | 4 |
| TOYOTA | 1SZ-FE | 2 |
| TOYOTA | 1W | 4 |
| TOYOTA | 1Z, 11Z | 4 |
| | | |
| VOLKSWAGEN | AER, ALL, ALD, ANV, AUC, BCA, BKY, AHW, AKK, AKD, ANM, ANW | 2 |
| VOLKSWAGEN | AAK, AAU, AAV, ACM, AEV, ALM, ABU, ADX, AEA, AEX, AEE | 4 |
| VOLKSWAGEN | AAF, ACU, AEN, AET, AEU, APL, AVT | 4 |
| VOLKSWAGEN | AFB, AKN, BAU, BDG, BDH | 4 |
| VOLKSWAGEN | ALZ, ANA, AVU, AYD, BFQ, BFS, BGU, BSE, BSF | 2 |
| VOLKSWAGEN | DF, DG, DH, DJ, GW, MV, SS, SR | 2 |
| | | |
| VOLVO | D50A, D50B, TD50A, TD50B, TD60, TD61, TD63 | 4 |
| VOLVO | TD70, TD71, TD73 | 4 |
| VOLVO | TD100, TD101, TD102, TD103, THD100, THD101, HD102, THD103 | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | |
|-------|--|---|
| VOLVO | D120, TD120, TD121, TD122, TD123, TID121 | 4 |
| VOLVO | D.16A, D16B, D16C, TD162 | 4 |

TOYOTA

| CNA NO. | OEM NO. | ENGINE MODEL | SET NO. | DIAMETER | PCS/SET |
|-----------|---------|------------------|----------|----------|---------|
| CNA-T1001 | T022A | | TW-1400A | 66 | 4 |
| CNA-T1002 | TO40A | | TW-1417A | | 4 |
| CNA-T1003 | T038A | 1C 2C 3C | TW-1408A | | 4 |
| CNA-T1004 | T030A | D 2D | TW-1040B | 100 | 4 |
| CNA-T1005 | T712A | 1DZ | | | 4 |
| CNA-T1006 | T713A | 1DZ(98-) | | | 4 |
| CNA-T1007 | T025A | | TW-1415A | | 4 |
| CNA-T1008 | T027A | 3E 5E | | | 4 |
| CNA-T1009 | T044A | 3F | TW-1413A | | 4 |
| CNA-T1010 | T708A | 1FZ-FE | | | 4 |
| CNA-T1011 | TO21A | | TW-1402A | | 4 |
| CNA-T1012 | T032A | H 2H | TW-10636 | | 4 |
| CNA-T1013 | T034A | 12H-T | | | 4 |
| CNA-T1014 | T706A | 1HZ 1HD-T | | | 4 |
| CNA-T1015 | T702A | | | | 4 |
| CNA-T1016 | T720A | 1KZ | | | 4 |
| CNA-T1017 | T037A | | TW-1161A | 82 | 4 |
| CNA-T1018 | TOO1H | M 2M 4M 3M 5M | TW-1006B | 80 | 4 |
| CNA-T1019 | TOO4A | | TW-1005B | | 4 |
| CNA-T1020 | T706A | | | | 4 |
| CNA-T1021 | TOO1H | 3R 5R | | 80.01 | 4 |
| CNA-T1022 | TO11A | 5R 16R 16R-U | TW-1133K | 80 | 4 |
| CNA-T1023 | T003A | 12R | TW-1007A | 76 | 4 |
| CNA-T1024 | TO20A | 22R (81-) | TW-1405A | | 4 |
| CNA-T1025 | T703A | | | | 4 |
| CNA-T1026 | TO18A | 1S 2S 3S 12T 13T | TW-1117K | | 4 |
| CNA-T1027 | T710A | 3S-FE 5S-FE | | | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------|-------|------------|----------|----|---|
| CNA-T1028 | T029A | 1VZ-FE | | | 4 |
| CNA-T1029 | TO18A | Y 2Y 3Y 4Y | TW-1117K | 76 | 4 |
| CNA-T1030 | T721A | 1Z 11Z | | | 4 |

NISSAN

| | | | | | |
|-----------|--------|-------------------------------|-----------|-------|---|
| CNA-T2001 | TO51H | D11 D12 | TW-1000B | | 4 |
| CNA-T2002 | TO71H | G18 G20 | TW-1066J | | 4 |
| CNA-T2003 | T094A | | | | 2 |
| CNA-T2004 | TO51H | JJ13 J15 J16 | TW-1000B | 69.85 | 4 |
| CNA-T2005 | T093A | | TW-1202A | | 2 |
| CNA-T2006 | T098H | SR18 SR20 | | | 2 |
| CNA-T2007 | T062H | ED30 ED33 FD33 ED6 FD6 | T3023A | | 4 |
| CNA-T2008 | T092H | | T3329L | | 4 |
| CNA-T2009 | T067H | ND6 NE6 | TW-1083K | 117.8 | 4 |
| CNA-T2010 | T076H | | T3307K | 127.8 | 4 |
| CNA-T2011 | T063H | RD8 RD8-T | TW-1118K | | 4 |
| CNA-T2012 | TO80H1 | SD20 SD22 SD23 SD33 TD23 TD25 | TW-1028GP | 93.8 | 4 |
| CNA-T2013 | T075H | UD3 UD33 UD4 UD5 UD6 | | | 4 |

MITSUBISHI

| | | | | | |
|-----------|-------|----------------------|--------|-------|---|
| CNA-T3001 | T127A | | T7061A | | 2 |
| CNA-T3002 | T103H | | T768A | | 2 |
| CNA-T3003 | T135A | | T7200A | | 2 |
| CNA-T3004 | T123A | | T7285A | | 4 |
| CNA-T3005 | T103H | | | 82.85 | 2 |
| CNA-T3006 | T133A | 4M40 | | | 4 |
| CNA-T3007 | T108H | 4D30 4D31 4D32 | T6029L | 103.5 | 3 |
| CNA-T3008 | T110H | 4DR1 4DR5 4DR50 | T650L3 | | 3 |
| CNA-T3009 | T112H | 6D106D116D146D156D16 | T6320L | | 3 |
| CNA-T3010 | T129H | 6D16A | T6326L | | 3 |
| CNA-T3011 | T107H | 6D20 6D21 6D22 | T605K | | 3 |
| CNA-T3012 | T114H | | T607K | | 3 |
| CNA-T3013 | T108H | 6D31 6D31-T | T6029L | | 3 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------|-------|------------------------------------|--------|--|---|
| CNA-T3014 | T106P | 6DB1 6BD10 | T6302K | | 4 |
| CNA-T3015 | T107H | | T605K | | 3 |
| CNA-T3016 | T110H | 6DR5 6DR50 | T650L3 | | 3 |
| CNA-T3017 | T108H | | T618L1 | | 3 |
| CNA-T3018 | T114H | | T607K | | 3 |
| CNA-T3019 | T124H | 8DC2 8DC4 8DC6 8DC7 8DC61 8DC81 | T617K | | 3 |
| CNA-T3020 | T128H | S2E S3E S4E S6E | T625K | | 3 |
| CNA-T3021 | 7131A | S4K S6K | | | 3 |

ISUZU

| | | | | | |
|-----------|--------|--|--------|------|---|
| CNA-T3022 | T160H | 2AA1 2AB1 2AE1 3AA1 3AB1 3AD1 3AE1 3AF1 | T4651A | | 2 |
| CNA-T3023 | T192A | | T510A | | 2 |
| CNA-T3024 | T806A | | T512A | | 2 |
| CNA-T3025 | T168H | 4BA1 4BB1 4BC1 | T434K | | 4 |
| CNA-T3026 | T173H | 4BA1 4BB1 4BC1 4BD1 4BE1 4BG1 | T428K | 101 | 4 |
| CNA-T3027 | T187A | 4BC1 | | | 2 |
| CNA-T3028 | T171A1 | 4FA1 4FB1 4FC1 4FD1 4FE1 G130 G150 G161 | T521A | 80 | 2 |
| CNA-T3029 | T801A | 4HF1 | | | 3 |
| CNA-T3030 | T184A | | T4650A | 93 | 2 |
| CNA-T3031 | T185A | 4JB1 | | 93 | 2 |
| CNA-T3032 | T181A | 4XC1 4XE1 4XC1-T | T5038A | | 2 |
| CNA-T3033 | T163H | | | | 4 |
| CNA-T3034 | T167H | 6RA1 6RB1 E120 E120-T | | | 4 |
| CNA-T3035 | T186H | 6SA1 6SD1 | T444K | | 4 |
| CNA-T3036 | T179H | 8PA1-8PC110PA1-10PC1 | T438A | | 4 |
| CNA-T3037 | T157H | C190 C220 C223 | T4650A | | 2 |
| CNA-T3038 | T169H | C330 D500 | T433K | | 4 |
| CNA-T3039 | T155H | DAI20 GD150 Da220 | | 99.9 | 4 |
| SUZUKI | | | | | |
| CNA-T4021 | T651A | F5A F8A F10A Y64 | T5983A | | 2 |
| CNA-T4022 | T653A | F5A F5A-T | T5901A | | 2 |
| CNA-T4023 | T658A | F6A | | | 2 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------|-------|-------------------|--------|----|---|
| CNA-T4024 | T655A | G10 G10-TG13 G13B | T5985A | 68 | 2 |
| CNA-T4025 | T657A | G15 G16 | T5987A | | 2 |

HINO

| | | | | | |
|-----------|-------|---|--------|--|---|
| CNA-T3040 | T203P | -77 | T1110K | | 4 |
| CNA-T3041 | T202H | DM100 DQ100 | T1032K | | 4 |
| CNA-T3042 | T201H | DS50 DS60 DS70 DS80 | T1100K | | 4 |
| CNA-T3043 | T204P | EB100 EB200EB300 | T1120K | | 4 |
| CNA-T3044 | T213P | EB300 EB400 | | | 3 |
| CNA-T3045 | T205H | EC100 | T1145K | | 4 |
| CNA-T3046 | T210H | EF100 EF100-T EF300 | T1127K | | 3 |
| CNA-T3047 | T212H | EF100 EF300 EF350 EF500 | T1128K | | 3 |
| | | EF700 EF100-T EG100 | | | |
| CNA-T3048 | T221H | EF550 EF750 EF750-T | T1123K | | 3 |
| CNA-T3049 | T220H | | T1104K | | 4 |
| CNA-T3050 | T214H | EK100 EK300 K13C | T1106K | | 3 |
| CNA-T3051 | T215H | EL100 78-80 | T1137K | | 3 |
| CNA-T3052 | T219H | EL100 EM100 | T1138K | | 4 |
| | | Ep100 EP100-T 80- | | | |
| CNA-T3053 | T211P | ER100 ER200 | T1112K | | 3 |
| CNA-T3054 | T218H | HO6C HO6C-T HO7C HO7D JO5C JO5C-T1 JO7C JO8C | T1108K | | 4 |
| CNA-T3055 | T216H | 1W WO4D WO4DT | T133K | | 4 |
| | | WO6D WO6DT WO6E | | | |
| CNA-T3056 | T | WO6D | T1033K | | 4 |

DAIHATSU

| | | | | | |
|-----------|--------|--------------------------|-------|----|---|
| CNA-T3057 | T255A | AB 1 0 AB20 AB50 AD AB31 | T162A | | 2 |
| | | AB51 AB40 CB10 CL1 0 | | | |
| CNA-T3058 | T280A | CB70-T CL50-T 70-T | T166A | | 2 |
| CNA-T3059 | T275A | DG | | 94 | 2 |
| CNA-T3060 | T283A1 | HC HD | T180A | | 2 |

MAZDA

| | | | | | |
|-----------|-------|-------------------|-------|--|---|
| CNA-T4001 | T317A | B1 B3 B5 B6 BJ BP | T808A | | 2 |
|-----------|-------|-------------------|-------|--|---|



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------|-------|----------------|--------|------|---|
| CNA-T4002 | T313A | E1 E3 E5 TC UC | T8122 | 69 | 4 |
| CNA-T4003 | T312A | HA SL SL-T | T8360A | | 4 |
| CNA-T4004 | T304A | MA NA UB VB VC | T833W | 86 | 4 |
| CNA-T4005 | T303A | PB TATB | T8125A | 78 | 4 |
| CNA-T4006 | T324A | PN | T8416A | | 2 |
| CNA-T4007 | T316A | R2 RF | T8418A | 84.4 | 4 |
| CNA-T4008 | T314A | S2 | T8380A | | 4 |
| CNA-T4009 | T310A | TC | T8128A | | 4 |
| CNA-T4010 | T307A | XAXB YAZB | T8400A | 95 | 4 |

KOMATSU

| | | | | | |
|-----------|-------|--------------------------|-------|--|---|
| CNA-T4011 | T408H | 4D95L 4D95S 6D95L | T888L | | 3 |
| CNA-T4012 | T403H | 4D92-14D92-24D92-34D94-2 | T856L | | 4 |
| CNA-T4013 | T404A | 4D105-5 S4D105-5 6D | T865L | | 3 |
| | | 105-1 S6D105-1 SA6D110-1 | | | |
| CNA-T4014 | T401P | 4D120 15TYPE | | | 4 |
| CNA-T4015 | T402P | 6D130 CUMMINS | | | 4 |

HONDA

| | | | | | |
|-----------|--------|------------------------------------|--------|--|---|
| CNA-T4016 | T451A1 | A18AA2OAD12A D13C D15AD15B D15Z | T9800A | | 2 |
| | | EB1EEEE5 EC ED EF EK EJ EN | | | |
| | | EM EP ER ER-T ES ET EV EW EY | | | |
| CNA-T4017 | T461A | B16A | T9750A | | 2 |
| CNA-T4018 | T458A | B20A ZC | T990A | | 2 |
| CNA-T4019 | T459A | C25AC27A F20A F22B | T998A | | 2 |
| | | H23A F18B F20B G25AG20A | | | |
| CNA-T4020 | T458A | ZC | | | 2 |

CAM BUSH

TOYOTA

| CNA NO. | OEM NO. | ENGINE MODEL | SET NO. | DIA | PCS |
|-----------|---------|--------------|----------|----------|-----|
| CNA-C1001 | CO35L | B 2B | SH-1121B | 51.06 | 3 |
| CNA-C1002 | CO28L | 3B 13B | | 56-57.58 | 5 |
| CNA-C1003 | C040L | B 3B 11B 13B | SH-1417B | 56-56.53 | 5 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------|--------|-------------------------|----------|-------------|----|
| CNA-C1004 | C048L | B | C9494W | 57-57.58 | 5 |
| CNA-C1005 | CO30P | D 2D | | 60.06 | 4 |
| CNA-C1006 | C713L | 1DZ | | 50.8-51.03 | 3 |
| CNA-C1007 | CO37A | | SH-1161A | 38.04 | 6 |
| CNA-C1008 | C042A | L 2L 3L 5L 2L-T | SH-1431A | 38/31 | 10 |
| CNA-C1009 | CO31L | F | SH-1123B | 47.5-52 | 4 |
| CNA-C1010 | CO32L | H 2H | SH-1063B | 51.03 | 4 |
| CNA-C1011 | CO34A | 2H 12H-T | SH-1403B | 55.03 | 4 |
| CNA-C1012 | C706A | 1HZ 1HD-T | | 38.04 | 2 |
| CNA-C1013 | COO2L1 | K 2K 3K 4K 5K 3K-U 5K-J | SH-1056B | 46.5-48.03 | 4 |
| CNA-C1014 | COO9L | | SH-1068B | 38.04 | 8 |
| CNA-C1015 | COO5L | | DB-1171B | 37-44.98 | 2 |
| CNA-C1016 | COO4L | | SH-1062B | 51 | 3 |
| CNA-C1017 | C706A | | | 38.04 | 2 |
| CNA-C1018 | C012L | 5R | SH-1013B | 50.03 | 5 |
| CNA-C1019 | C003L | 12R | SH-1060B | 50.02 | 3 |
| CNA-C1020 | C018L | T 2T 2T-G 3T | SH-1104B | 49-50 | 5 |
| CNA-C1021 | C041L | Y 2Y 3Y 4Y | SH-1407B | 49-50 | 5 |
| CNA-C1022 | C721A | 1Z | | 50.75-55.23 | 3 |
| CNA-C1023 | C719A | 1Z | | 55.23 | 3 |
| CNA-C1024 | C722A | 11Z | | 51.23-55.43 | 4 |

NISSAN

| | | | | | |
|-----------|-------|-----------------|----------|-------------|---|
| CNA-C2001 | CO60L | A10 A12 A14 A15 | SH-1019B | 44.46-47.03 | 5 |
| CNA-C2002 | CO52L | H2O U20 | SH-1003B | 44.45-48.66 | 3 |
| CNA-C2003 | CO51L | JJ13 J15 J16 | SH-1006B | 44.45-48.66 | 3 |
| CNA-C2004 | C072L | P PF | SH-1002B | 51.66-52.71 | 4 |
| CNA-C2005 | C087A | TD23 TD25 Td27 | SH-1190B | 53-53.83 | 5 |

MITSUBISHI

| | | | | | |
|-----------|-------|---------------------|--------|-------------|---|
| CNA-C2006 | C117L | | C628W | 57-58.52 | 3 |
| CNA-C2007 | C109L | 4DR5 4DR50 | C650W1 | 57.02 | 3 |
| CNA-C2008 | C129A | 6D10 6D11 6D14 6D15 | C621W | 62.08-62.83 | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------------|--------|----------------------------|--------|-------------|----|
| CNA-C2009 | C110L | | C652W1 | 57.02 | 4 |
| CNA-C2010 | C131L | S4K | | 57.2 | 3 |
| CNA-C2011 | C132L | S6K | | 57.2 | 4 |
| HINO | | | | | |
| CNA-C2034 | C202L | DM100 DQ100 | C132W | 49-58 | 5 |
| CNA-C2035 | C205L | EC100 | C145W | 56.63-59.53 | 4 |
| CNA-C2036 | C216L | 1W WO4D WO4DT | C133W | 59.6-60 | 3 |
| CNA-C2037 | C217L | WO6D WO6DT WO6E | C134W | 59.6-60 | 4 |
| DAIHATSU | | | | | |
| CNA-C2038 | C276A | DL DL-T DG | C177A | 50.03 | 3 |
| ISUZU | | | | | |
| CNA-C3001 | C168L | 4BA1 4BB1 | C528W1 | 60.05 | 4 |
| CNA-C3002 | C177L | 4BA14BB14BC14BD14BG1 | C434W1 | 60.05 | 3 |
| CNA-C3003 | C176L | 4FA14FB14FC14FD14FE1 | C516W | 31.02 | 10 |
| CNA-C3004 | C801L | 4HF1 | | 43.03 | 10 |
| CNA-C3005 | C184A1 | 4JA1 4JB1 4JC1 4JD1 | | 54.1 | 3 |
| CNA-C3006 | C173L | 6BB1 6BD1 6BF1 6BG1 | C433W1 | 60.05 | 6 |
| CNA-C3007 | C157L | C220 DL201 | | 48.03 | 3 |
| CNA-C3008 | C153L | C221 | C525W | 52.04 | 3 |
| CNA-C3009 | C168L | C330 | | 60.05 | 4 |
| CNA-C3010 | C155A | DAI20 GD150F GD150 DA640 | | | 4 |
| CNA-C3011 | C156A | DH100 DH100H | | | 7 |
| CNA-C3012 | C171L | G130 G150 G160 G161 | C513W | 48.03 | 3 |
| CNA-C3013 | C172L | G161 G161WG180W | C514W | 33 | 10 |
| MAZDA | | | | | |
| CNA-C3014 | C304L | MA NA UB VB VC | C8130W | 49.03 | 6 |
| KOMATSU | | | | | |
| CNA-C3015 | C408H | 4D95L 4D95S | C890L | 53.53 | 3 |
| CNA-C3016 | C409H | 6D95L | | 53.53 | 4 |
| CNA-C3017 | C404H | 4D105-5 S4D105-5 | C859L | 57.53 | 3 |
| CNA-C3018 | C405H | 6D105-1 S6D105-1 SA6D110-1 | C865L | 57.53 | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

PIN BUSH

TOYOTA

| | | | | | |
|-----------|-------|--------------------|----------|-------|---|
| CNA-P1001 | PO43H | 4A-GE 4A-GZE | PB-1121J | 22.03 | 4 |
| CNA-P1002 | P035H | | PB-1401J | 33.14 | 4 |
| CNA-P1003 | PO40H | 3B | P9493L | 36.03 | 4 |
| CNA-P1004 | P028H | 11B 13B | | 38.01 | 4 |
| CNA-P1005 | PO48H | 3B 11B 13B 14B 15B | PB-1408J | 36.03 | 4 |
| CNA-P1006 | P038H | 1C 2C 1C-T | | 30.03 | 4 |
| CNA-P1007 | PO45H | | PB-1040J | 30.03 | 4 |
| CNA-P1008 | P030P | D 2D | | 40.15 | 6 |
| CNA-P1009 | P030H | | | 38.1 | 6 |
| CNA-P1010 | P713H | 1DZ | PB-1413J | 30.03 | 4 |
| CNA-P1011 | PO44H | 3F | | 24.05 | 6 |
| CNA-P1012 | P708H | | PB-1402J | 28.03 | 6 |
| CNA-P1013 | PO47H | | | 20.02 | 6 |
| CNA-P1014 | P021H | 1G-GT 1G-GZ | | 22.03 | 6 |
| CNA-P1015 | P034H | H 2H | PB-1403J | 30.01 | 6 |
| CNA-P1016 | P015H | 2H | | 33.03 | 6 |
| CNA-P1017 | PO49H | 12H-T | | 36.03 | 6 |
| CNA-P1018 | P707H | 1HZ | | 32.03 | 6 |
| CNA-P1019 | P709H | 1HD-T | PB-1063J | 36.03 | 6 |
| CNA-P1020 | P032H | J 2J | | 30.01 | 4 |
| CNA-P1021 | P702H | | PB-1056J | 24.03 | 6 |
| CNA-P1022 | POO2H | | | 20.02 | 4 |
| CNA-P1023 | P720H | | PB-1411J | 37.03 | 4 |
| CNA-P1024 | P039H | | | 32.03 | 4 |
| CNA-P1025 | PO42H | L 2L | | 30.03 | 4 |
| CNA-P1026 | P037H | 2L-T 3L 5L | PB-1051J | 32.03 | 4 |
| CNA-P1027 | POO5H | | | 24 | 6 |
| CNA-P1028 | PO46H | | | 26.53 | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------|-------|---------------|----------|-------|---|
| CNA-P1029 | POO4H | | PB-1062J | 22 | 4 |
| CNA-P1030 | P706H | | | 32.03 | 5 |
| CNA-P1031 | POO1H | | | 27.02 | 4 |
| CNA-P1032 | P012H | 5R | PB-1046J | 24.05 | 4 |
| CNA-P1033 | P003H | 12R | PB-1035J | 22.02 | 8 |
| CNA-P1034 | P010H | 16R 18R 18R-G | PB-1068J | 24.05 | 4 |
| CNA-P1035 | P703H | | | 27.03 | 4 |
| CNA-P1036 | P710H | 3S-FE 5S-FE | | 24.03 | 4 |
| CNA-P1037 | P704H | 3VZ-FE | | 24.03 | 6 |
| CNA-P1038 | P721H | 1Z | | 36.03 | 4 |
| CNA-P1039 | P722H | 11Z | | 36.03 | 6 |

NISSAN

| | | | | | |
|-----------|--------|---------------------|----------|-------|----|
| CNA-P2001 | P052H | H2O U20 | PB1002J | 24.02 | 4 |
| CNA-P2002 | P054H | LD20 LD20T | | 28.02 | 4 |
| CNA-P2003 | P067H | FE6 FE6-T | P310L | 40.08 | 6 |
| CNA-P2004 | P076H | | PB-1084J | 50 | 6 |
| CNA-P2005 | P063H | RD8 RD8-T | PB-1118J | 50 | 8 |
| CNA-P2006 | P064H | RD10 RD10-T | PB-1119J | 50 | 10 |
| CNA-P2007 | P080H | SD20 SD22 | PB-1029J | 29.02 | 4 |
| CNA-P2008 | P085H | SD20 SD22 SD23 SD25 | PB-1182J | 29 | 4 |
| CNA-P2009 | P081H | SD33 SD33-T | PB-1058J | 29.02 | 6 |
| CNA-P2010 | P087H1 | TD25 | PB-1192J | 31 | 4 |
| CNA-P2011 | P096H1 | TD 42 | P338L | 31 | 6 |

MITSUBISHI

| | | | | | |
|-----------|-------|---------------------|--------|-------|---|
| CNA-P2012 | P103H | | P768L | 21 | 4 |
| CNA-P2013 | P113K | 4D55 4D56 | P777L | 32.03 | 4 |
| CNA-P2014 | P133H | | | 33.03 | 4 |
| CNA-P2015 | P117H | 4D30 4D31 4D32 | P6331L | 37.02 | 4 |
| CNA-P2016 | P121H | | P6029L | 37.03 | 4 |
| CNA-P2017 | P109H | 4DR5 5DR50 | P651L | 31.03 | 4 |
| CNA-P2018 | P112H | 6D10 6D11 6D14 6D15 | P620L | 41.08 | 6 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------------|--------|---------------------------|--------|--------|---|
| CNA-P2019 | P110H | 6DR5 6DR50 | P652L | 31.03 | 6 |
| CNA-P2020 | P125H | 8DC28DC48DC68DC78DC8 | PP607L | 51.02 | 2 |
| CNA-P2021 | P124H | 8DC9 8DC10 8DC11 | PP617L | 56.1 | 2 |
| CNA-P2022 | P131H | S4K S6K | | 37.02 | 2 |
| HINO | | | | | |
| CNA-P2022 | P202H | DM100 DQ100 | P132L | 32.03 | 6 |
| CNA-P2023 | P205H | EC100 | P145L | 35.53 | 6 |
| CNA-P2024 | P210H | EF100 Ef300 EF350 Ef500 | P106L | 55.03 | 8 |
| | | Ef700 EF100-T EG100 | | | |
| CNA-P2025 | P208H1 | EHS00 EH700 | P1108L | 43.03 | 6 |
| CNA-P2026 | P216H | 1W WO4D WO4DT | P133L | 39.03 | 4 |
| CNA-P2027 | P217H | WO6D WO6DT WO6E | P134L | 39.03 | 6 |
| DAIHATSU | | | | | |
| CNA-P2028 | P275H1 | DG DL DL-T | P1777L | 29.02 | 4 |
| CNA-P2029 | P276H | DL DL-T | | 31.03 | 4 |
| CNA-P2030 | P | DL DL-T | | 29.025 | 4 |
| ISUZU | | | | | |
| CNA-P3001 | P177H | 4BA1 4BC1 | | 38.03 | 4 |
| CNA-P3002 | P170H | 4BA1 4BC1 | P433L | 36.03 | 4 |
| CNA-P3003 | P168H | 4BA14BB14BC24BD14BE14BG1 | P434L | 38.03 | 4 |
| CNA-P3004 | P187H | 4BC1 | | 25.02 | 4 |
| CNA-P3005 | P176H | 4FA1 4FB1 4FC1 4FE1 | P516L | 28.03 | 4 |
| CNA-P3006 | P801H | 4HF1 | | 40.02 | 4 |
| CNA-P3007 | P184H1 | 4JA1 4JB1 4JC1 4JD1 | P450L | 34.1 | 4 |
| CNA-P3008 | P173H | 6BB1 6BD1 6BF1 6BG1 | P436L | 38.03 | 6 |
| CNA-P3009 | P167H | 6RA1 6RB1 E120 E120-T | P435L | 56.04 | 6 |
| CNA-P3010 | P186H | 6SA1 6SD1 | P444L | 43.03 | 6 |
| CNA-P3011 | P160H | 3AA1 3AB1 C190 C240 (81-) | P526L | 30.03 | 4 |
| CNA-P3012 | P | C190 C223 | P535L | 30.025 | 4 |
| CNA-P3013 | P157H | C221 | P503L | 28 | 4 |
| CNA-P3014 | P177H | C330 | P529L | 38.03 | 4 |



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------|-------|--------------------------|-------|-------|---|
| CNA-P3015 | P173H | D500 | | 38.03 | 6 |
| CNA-P3016 | P154H | DAI20 GD150 GD150F DA640 | | 40.03 | 6 |
| CNA-P3017 | P164H | DA220 | P403L | 40.03 | 4 |
| CNA-P3018 | P166H | DH100 DH100H | P415L | 51.04 | 6 |
| CNA-P3019 | P171H | G130 G150 G160 G161 | P513L | 25.42 | 4 |
| | | G180 G161WG161ZG200Z | | | |

MAZDA

| | | | | | |
|-----------|-------|----------------------|---------------|-------|---|
| CNA-P3020 | P319H | HA | P840L | 34.96 | 4 |
| CNA-P3021 | P312H | HA | P836L | 33.11 | 4 |
| CNA-P3022 | P304H | MA NA UA UB VA VB VC | P8000PB-1114J | 25.02 | 4 |
| CNA-P3023 | P303H | PB PC TA TB | P8125L | 23.02 | 4 |
| CNA-P3024 | P324H | PN | P816L | 28.02 | 4 |
| CNA-P3025 | P316H | R2 RF | P818L | 28.03 | 4 |
| CNA-P3026 | P336H | R2 Therefore | P838L1 | 28.03 | 4 |
| CNA-P3027 | P314H | S2 | P837L | 31.04 | 4 |
| CNA-P3028 | P318H | SL SL-T | P842L | 37.11 | 4 |
| CNA-P3029 | P320H | ZB | | 34.96 | 6 |

KOMATSU

| | | | | | |
|-----------|-------|----------------------------|-------|-------|---|
| CNA-P3044 | P408H | 4D95L 4D95S | P890L | 33.03 | 4 |
| CNA-P3046 | P409H | 6D95L | | 33.03 | 6 |
| CNA-P3047 | P403H | 4D92-1 4D92-2 4D92-34D94-2 | P856L | 36.03 | 4 |
| CNA-P3048 | P412H | | | 33.03 | 4 |
| CNA-P3050 | P404H | 4D105-5 S4D105-5 | P859L | 40.07 | 4 |
| CNA-P3052 | P405H | 6D105-1 S6D105-1 | P865L | 40.07 | 6 |
| | | SA6D110-1 | | | |

SUZUKI

| | | | | | |
|-----------|-------|---------------|--|-------|---|
| CNA-P3053 | P652H | F5A F5A-T Y64 | | 18.02 | 3 |
| CNA-P3054 | P651H | F8A F10A | | 18.02 | 4 |
| CNA-P3055 | P659H | F8A F10A | | 18.02 | 4 |
| CNA-P3056 | P654H | Y64 F8B | | 18.02 | 3 |

MERCEMES-BENZ



CANDA MOTOR PARTS

Tel:0086-577-86755433 Fax:0086-577-86755422

Email:chester@mail.wzptt.zj.cn

| | | | | | |
|-----------|---------|--------|--|--|--|
| CNA-P3057 | 55-2535 | OM352 | | | |
| CNA-P3058 | 55-3328 | OM402 | | | |
| CNA-P3059 | 55-2538 | OM355 | | | |
| CNA-P3060 | 55-2532 | OM616 | | | |
| CNA-P3061 | 55-2847 | OM360 | | | |
| CNA-P3062 | N082/7 | OM355 | | | |
| CNA-P3063 | N110/06 | OM403 | | | |
| CNA-P3064 | N075/07 | OM360 | | | |
| CNA-P3065 | N110/07 | OM424 | | | |
| CNA-P3066 | N049/4 | OM352 | | | |
| CNA-P3067 | N110/05 | OM 402 | | | |